

BOQ

Sub.: Repair of non working ceiling fans, exhaust fans from Hostels, AB-1 & AB-2 at IISER Mohali

S.No.	Description of items	Qty	Unit	Rate	Amount
1	Ceiling fans repair, size 1200 to 1400 mm including rewinding, bearing change, capacitor change and greasing	50	Nos		
2	Exhaust fan repair, size 18", including copper rewinding, capacitor and bearing change, greasing.	6	Nos		
3	Exhaust fan repair, size 15" and below, including copper rewinding, capacitor and bearing change, greasing.	2	Nos		
4	Exhaust fan repair, size 12" and below, including copper rewinding, capacitor and bearing change, greasing.	5	Nos		
	Total				

Contractor