

TECHNICAL EVALUATION

Name of Work: Repair of polycarbobnate sheet at IISER Mohali.

S. No	Name of Agency	Remark
1.	2.	3.
1	M/s Sudha Constructions, Chandigarh	The contractor has not provided similar work in nature as stipulated in NIQ, therefore, not qualified
2.	M/s Dilip Kumar Chandan, Mohali	The contractor has not provided similar work in nature as stipulated in NIQ, therefore, not qualified
3.	M/s Karanvir Singh Saini, Fatehgarh Sahib	Qualified
4.	M/s Sukhjit Singh, Mohal	Qualified

M/s Karanvir Singh Saini and M/s Sukhjit Singh are technically qualified