

BOQ

S.No.	Description of item	Qty	Unit	Rate	Amount
1/ 9.20	Providing and fixing ISI marked flush door shutters conforming to IS : 2202 (Part I) decorative type, core of block board construction with frame of 1st class hard wood and well matched teak 3 ply veneering with vertical grains or cross bands and face veneers on both faces of shutters.				
9.20.1	35 mm thick including ISI marked Stainless Steel butt hinges with necessary screws	6	sqm		
2/ 13.80	Providing and applying white cement based putty of average thickness 1mm, of approved brand and manufacturer, over the plastered wall surface to prepare the surface even and smooth complete.	375	sqm		
3/ 13.110	Finishing walls with textured exterior paint of required shade :				
13.110.2	Old work (One or more coats) applied @ 1.82 ltr/10 sqm.	400	sqm		
4./ 14.45	Distempering with oil bound washable distemper of approved brand and manufacture to give an even shade :				
14.45.1	Old work (one or more coats)	1750	sqm		
5/ 13.91	Removing dry or oil bound distemper, water proofing cement paint and the like by scrapping, sand papering and preparing the surface smooth including necessary repairs to scratches etc. complete.	375	sqm		
6/ 14.54	Painting with synthetic enamel paint of approved brand and manufacture of required colour to give an even shade :				
14.54.1	One or more coats on old work	145	sqm		
7/ NS	P/f of wire mesh door with wooden frame of standred CPWD specification.	2	No		
	Total				

Contractor